

FUNCTIONAL SPACE FORM

Building: Old Gym

Floor: Crawl Space/Basement/Tunnel

Inspector: Leland Sumptur

Inspector: Glenn Robinson

Date(s) of Inspection: 3/5/01

Certification # : 7ACT042301MOIMPR-323

Certification # : 7ACT042301MOIR-644

[illegible]

LEGEND:

SF = SQUARE FEET

LF = LINEAR FEET

PI = PIPE INSULATION

FG = FITTINGS

M = MISCELLANEOUS

TSI = THERMAL SYSTEM INSULATION

S = SURFACING

¹AMN = Not Applicable-Material is Negative

.A1= Assumed ACM- NOT sampled, would destroy material integrity

AA2= Assumed ACM- NOT sampled due to inaccessibility

ASSESSMENT CODES:

1. Damaged or significantly damaged thermal system insulation.
2. Damaged friable surfacing ACM.
3. Significantly damaged friable surfacing ACM.
4. Damaged or significantly damaged friable miscellaneous ACM.
5. ACBM with potential for damaged.
6. ACBM with potential for significant damaged.
7. Any remaining friable ACBM or friable suspected ACBM.